

HISTORIC AMERICAN ENGINEERING RECORD

INDEX TO PHOTOGRAPHS

HAER  
NY,  
60-055,  
2B-

Addendum to:

Old Croton Aqueduct  
Northern Waste Weir  
Snowden Ave. and Van Wyck St.  
Ossining  
Westchester County  
New York

HAER NY-109

Jack Boucher, photographer, 1978

- |          |  |
|----------|--|
| NY-109-1 | EXTERIOR VIEW LOOKING NORTH, SHOWING WASTE WEIR AT OSSINING.   |
| NY-109-2 | EXTERIOR VIEW LOOKING SOUTH. AQUEDUCT RUNS UNDERGROUND BENEATH STRUCTURE.  |
| NY-109-3 | EXTERIOR VIEW DETAILING MASONRY CONSTRUCTION.  |
| NY-109-4 | EXTERIOR VIEW LOOKING EAST. WATER IN THE AQUEDUCT CAN BE DIVERTED AT THE WASTE WEIR TO BE DISCHARGED INTO THE CULVERT IN FOREGROUND. |